

**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School : Lalitha Public School
2. Location : Wathoda Ring Road, Wardhaman Nagar, Nagpur
3. Plot Area : 10209.950 Sq.m
4. Plinth Area : 1811.4215 Sq.m
5. Number of Storey's : 04
6. Year of Construction of Building : 15 Years
7. **If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given** :
 - a) Name of the Engineer with qualification : Mr. Satish Raipure (B.E.M.Tech)
 - b) Address of Engineer : Mate Square, S.A Road, Nagpur
 - c) Set of Structural drawings used in the construction, if available : -
 - d) Name & address of Architect with qualification : Mr. Sandeep Ingole (B.Arch,A.I.I.A), Chhatrapati Sq. Wardha Road, Nagpur
8. **Whether the building has been constructed for the purpose**
 - a) School : YES
 - b) Residential Purpose and converted for use as a School : NO
9. **Materials used for roofs**
 - a) R.C.C. Slabs/R.B.C. Slabs : YES
 - b) R.S. Joist & Battons : YES
 - c) Wooden joists & Battons : YES
10. **Materials used for walls**
 - a) Mud Mortar : NO
 - b) Cement Mortar : YES
 - c) Lime Mortar : NO
11. **Flooring**
 - a) Conglomerate : NO
 - b) Terrazo : YES
 - c) Brick Paving. : YES
12. **A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows (Attached)**



Signature with Stamp of the seal
Of the School/Institution.


**PRINCIPAL
LALITHA PUBLIC SCHOOL
NAGPUR.**

PART-II

(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated10/6/2024..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used)
.....Two years from date of issue of this certificate.....

Satish Raipure
✓ 10/6/2024



Sub Divisional Engineer,

SATISH RAIPURE
Structural & Consulting Engineer
102, Vignaharta Apartments,
S. A. Road, Shraddhanand Peth,
Nagpur - 440022



Ref. No.: SSR/20-21/06/12

Date: 18.06.2021

STRUCTURAL ASSESSMENT REPORT

NAME OF THE WORK: Existing Building of Lalitha Public School, Wardhaman Nagar, Ring Road, Nagpur. 440035.

As per the request of Management of the above subjected school, I visited the above said premises 10.06.21, to assess the Structural Safety of the building. The said building is a Ground plus three storied RCC framed structure & was constructed in 2006-07.

The following are the observations –

1. The structure is in good condition & Maintained properly.
2. No settlement is observed anywhere.
3. Floor is in good condition, no settlement is observed.
4. Structural arrangement has not been changed at any location.
5. Three RCC Over Head tanks of approx. 10,000 ltrs capacity are seen in good condition.
6. Non destructive testing has been carried out at major locations. The results of the testing are satisfactory.

Based on the observations, I am of the opinion that, **the building is safe for the purpose it is intended.**

Hence this Certificate.

This certificate is valid for 2 years from the date of issue.

Satish Raipure

